## **Work Order**

Public Works and Maintenance Labourers read Work Orders to find out what to do.

Look at the OMMS Work Order.

Task

When was the work scheduled?

1

Task

Where is the job?

2

Task

What was the problem with the old manhole cover?

3

Task

Why didn't the crew install the new manhole cover?

4

Report Date: 04-Feb-2008 by: CARLOR
OMMS Work Order Page 1 of 1
M.A. 218916 Infrastructure: Manhole Group: Drainage Operations Activity: RPF Replace Frame & Cover
Scheduled Date: 19-JAN-2008 Crew: 643 DENNIS Group: Drainage Operations Crew Type: Drainage System Serviceman
Complete Date: Time: Crew: Name:
Note: replace old worn out frame new cover sits too high
Perf Date 19-JAN-2008 Issue: 29306 Received: 19-JAN-2008 Complete Date: 19-JAN-2008
Issue Note: old fashioned thin mh cover cracked. needs new frame for new style mh
cover, did not put new cover on as graders would wreck it because it sits too high cad 928 32 22 mh 224801
Route Id: Cad: 9283222 Year: 1951 Fac Status: INU Fac Type: MH Flow: SAN Fac Id: 224801Location: LS 73 AVE - 116 ST Assoc Note: