

Automotive 12

Autobody inspection

Mark Iversen

Vehicle Body

2015 Ram 1500 4x4



Tire Tread Depth



- Aprox. 9/32 (ruler doesn't show 32 and has gap area)

Tire Size and Manufacturing Date

Tire size - 265/70R17





Tire Inflation Specifications

- 40 PSI as shown in door jam

Pads and Rotors




Rotor – Clean and in good condition
Pads - unable to see with tire on

Brake Hoses



Hoses – in good
condition



Paint Defects



- Some scratches near handle of tailgate

Shocks and Springs



Shocks and springs in good condition





CV Drive Axles

No leaks or tears



Tie Rods and Ball Joints

- Good condition

Exhaust Pipe and Mufflers

- No punctures or damage




Body and Frame Rust



Small rust on rear Bumper

Air Filter

- Air Filter in good condition




Brake Fluid

- Brake fluid level good
- Colour slightly dark but ok



Coolant and Hoses

- Hoses in good condition
- Coolant levels correct




Battery

- Clean and free of debris




Drive Belts



Oil Level and Type

- Oil in need of replacing
- 5w - 20



Power Steering

- Slightly in need of adding more
- Colour good and clean



Transmission Fluid

- Filled and clean

